Product Data Sheet

Cobra Bond Coat



Cobra Bond Coat is a single component, just add water, cement-based bonding agent specifically developed for use with Cobra Stampable Overlay. Cobra Bond Coats only functions is to join the stampable overlay to the substrate.

This product has a high cement content and dry-copolymer agent which create a premier bond, while the fin aggregate micro dowels into the substrate or area to be patched.

APPLICATIONS

Cobra Bond Coat has an infinite number of applications, but is most commonly used for:

- Interior & Exterior Stampable Overlay Three Dimensional Overlays
- Interior & Exterior Stamped Patterns
- Interior & Exterior Sprayable Concrete

BENEFITS

Cobra Bond Coat has a large list of benefits, including but not limited to;

- Stronger Bond Then Liquid Polymers
- Tintable to match overlay material color
- Fix existing problems in hard scape

SURFACE PREPARATION

- 1. Clean The surface must be free of dust, dirt, oil, grease, paints, glues, non- acrylic sealers, curing agents, efflorescence, chemical contaminants, rust, algae, mildew and other foreign matter that may serve as a bond breaker.
- 2. Cured Any Concrete must be sufficiently cured to have sufficient hydration, approximately 7-14 days depending on temperatures and humidity.
- 3. **Sound** No system should be placed on concrete that is flaking, spalling, or has hibernating spalling.
- 4. *Profiled* Proper profile should follow the standard established by the International Concrete Repair Institute (ICRI) Technical Guideline no. 03732 for **C**oncrete **S**urface **P**rofile (CSP).

PACKAGING

50 lbs bag

COVERAGE

50lbs bag varies widely due to profile, porosity of substrate, temperature, and how thirsty the concrete slab is: approximately 300 - 450 ft²

APPLICATION TEMPERATURE 50°F - 90°F

ODOR

N/A

CURE TIME

Foot Traffic - 24 hours Vehicular Traffic - 72 hours

SHELF LIFE

Under normal conditions: when kept dry and moisture free, out of direct sunlight, the shelf like of an unopened container is (12) months from the date of purchase. Storage must be under roof and off the floor. Avoid extreme temperatures. Rotate inventory to maintain product that is within limits.

MIXING RATIO

6-7 quarts of clean water to one 50lbs bag.

<u>info@cobrapolymers.com</u> 1-888-336-9339

Product Data Sheet

Cobra Bond Coat



TEMPERATURE / CURE

- 1. Air and substrate surface temperatures shall remain between 50°F 90°F during and within 48 hours of installation.
- 2. No precipitation should occur during or within 48 hours of installation.
- 3. Avoid high heat / or windy conditions. Attempt to minimize application during such harsh conditions by working during cooler hours. Keep materials shaded prior to mixing, running water until cool, and setting up temporary wall for wind blocks.

MIXING / APPLICATION

Full Bag- Mixing and Handling

- 1. Add 6-gy's water to a 5 Gallon Pail
- 2. Add 1 Color Pack if required
- 3. Mix with a handheld concrete mixer equipped with a cage mixing blade for a minimum of 15 seconds.
- 4. Slowly add the Bond Coat into the pail with mixer running.
- 5. Scrape side of pail with a margin trowel to make sure all the dry product is included into the mix.
- 6. Continent to mix for a minimum of 1 minute after all ingredients are fully mixed to achieve a lump-free consistency. Additional water can be added up to a total of 7 qts per 50lbs bag.

Small Batch - Mixing and Handling

3.

- 1. For each 4-qt. dry mix, add 1.5 qt. water.
- 2. Add the desired amount of water to bucket of an appropriate size.

Start adding the dry mix to the water while running the mixer. Mix with an appropriate sizes mixer.

- 4. Scrape the sides of the container to make sure that all the dry mixture is included in the wet mix.
- 5. Mix for a minimum of 1 minute until all the ingredients are fully mixed to achieve a lump free consistency.

CLEAN UP

Before the product dries, spills and tools can be cleaning up with water.

DISPOSAL

Follow local guidelines for disposing hazardous products.

LIMITATIONS

- For use by trained professionals.
- Not designed to be a wear surface.

CAUTIONS

KEEP OUT OF REACH OF CHILDREN. Product is flammable. Avoid sources of ignition. Keep areas of installation well ventilated.

Inhalation: Use NIOSH approved respirator for organic vapors.

Skin Contact: Skin contact may cause irritation. Remove contaminated clothing immediately and wash effected area with soap and water. Wash clothing before using again. If symptoms persist seek medical attention immediately.

Eyes: Wear Safety eye protection when installing this product. If contact occurs, flush eye with water for 15 minutes, seek medical attention

Further Information

Information relating to the safe handling of this product can be found in the Material Safety Data Sheet. Local Regulations concerning the safe handling of epoxy resin based coating materials must be observed. Suitable protective clothing including eye protection must be worn at all times.

info@cobrapolymers.com 1-888-336-9339